




Standard Presser Foot

This presser foot is used for regular overlock stitching. It can also be used for sewing in tape while overlocking the edge of the fabric.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40134861	40233699	A1501-800-0A0	A1501-130-0B0	A1501-655-0B0A
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A1501-634-0B0	A1501-613-0B0A	40131302	40122001	

Blind Stitch Presser Foot (For Right Needle)

This presser foot is used to sew blind hem stitching while overlocking the edge of the fabric.

With this presser foot, the fabric edge, folded in three, can be inserted and the guide plate and positioned so that stitching will not be visible from the right side of the fabric. Since this presser foot is designed specifically for use with the right needle, it cannot be used with the left needle of a two-needle sewing machine.



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138091	_	A9810-634-0A0A		
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9810-6	34-0A0A	_		

Universal Blind Stitch Presser Foot (For Right & Left Needle)

This presser foot is used to sew blind hem stitching, decorative flatlock or pintucks.


This presser foot can be used with either the right or the left needle and has a guide plate that can be moved within a wide range. Since the seam width can be adjusted, this presser foot is also useful for decorating by sewing along a folded edge with decorative flatlock or with roll hem (pintuck) stitches.



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40149058	40131946		A9521-634-0A0A	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9521-634-0A0A		40131946	_	

Elasticator Presser Foot

This presser foot is used for sewing in elastic tape while overlocking the edge of the fabric.






MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138095	40233726		A9815-655-0A0A	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9815-655-0A0A		40131947	_	

Cording Presser Foot

This presser foot is used for sewing on nylon thread or wire for crafts.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138099	_	A9820-655-0A0A		
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9820-655-0A0A		_		

Beading Presser Foot

This presser foot is used for sewing on strands of pearls, beads or sequins.


Braiding of a width of up to 4 mm as well as transparent or decorative threads can be sewn on. The strand can also be sewn in the middle of fabric by sewing along a folded edge with flatlock.



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138106	40131949		A9870-634-0A0A	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9870-634-0A0A		40131949	_	

Curved Beading Presser Foot

This presser foot is used for sewing on strands of pearls, beads or sequins along curves.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40149059	_	A9511-634-0A0A		
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9511-6	34-0A0A	_	_	

Piping Presser Foot

This presser foot is used for sewing on piping while overlocking the edge of the fabric.

Sew along the edge of the piping with the tubular part of the tape fed into the groove along the bottom of this presser foot. Use either both needles or only the left needle with this presser foot.



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138103	40131950		A9865-655-0A0A	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9865-655-0A0A		40131950	_	

Gathering Presser Foot

This presser foot is used for sewing together two pieces of fabric while creating gathers.

Using the differential feed, gathers can be created in only the lower piece. You can adjust the amount of fabric that is gathered by changing the differential feed between 1.5 and 2.0. Gathers can also be created in a single piece of fabric.



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40138121	40131948		A9860-655-0A0C	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
A9860-655-0A0C	_	40131948	_	

Taping Foot

This presser foot is used for sewing in tape while overlocking the edge of the fabric.



Feed the tape into the slot at the front of the presser foot, and adjust the guide according to the width of the tape. Use this presser foot to insert tape along shoulder seams in order to reinforce them.

MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
	40131951		_	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
_		40131951	_	

Chain Stitch Presser Foot

This presser foot is designed specifically for sewing chain stitches.




Use the left needle with this presser foot. (Be sure to remove the right and center needles before using this presser foot.)

MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655		
	<u> </u>					
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500			
	_	40177370				

Coverstitch Hem Guide

This guide is used for setting the folded width of the fabric and the stitching position for coverstitching.






MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
_			40122229	_
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
_			40177371	

Upper Looper Converter

Two-thread overlocking or flatlock can be sewn with a 3/4-thread overlock sewing machine.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D MO-735		MO-655
	_	A9825-634-0A0	A9130-777-0A0	A9825-634-0A0
MO-654DE MO-644D	MO-623	MO-50e MO-50eN MCS-1500		
A9825-6	534-0A0	_		

Waste Collector

This box collects scraps of fabric cut by the overlock sewing machine.



This is useful for throwing out all scraps after work is completed, without allowing them to scatter around the work area. When storing the sewing machine, accessories such as the foot controller can be stored in this box.

MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D MO-735		MO-655
40134096	_	A910-880-L000	A9108-130-000	A9108-202-000
MO-654DE MO-644D	MO-623	MO-50e MO-50eN MCS-1500		
A9108-2	202-000	<u>-</u>		

Extension Table Set

Attaching the extension table expands your workspace.




The included push pin makes sewing circles easy.

MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
_	40233733		_	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
	-	_		

Foot Control

This controller can be used to start/stop sewing and adjust the sewing speed with your foot.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655		
Please contact your local JUKI dealer						
MO-654DE MO-644D MO-623 MO-50e MO-50eN MCS-1500						

MO Attachment Set 8pcs

This is a set of eight presser feet that can be used for practical sewing or decorative stitching.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40149062	_		40123395	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
4012	3395	_		

MO Attachment Set 6pcs

This is a set of six presser feet that can be used for practical sewing or decorative stitching.

This set contains the following: Blind Stitch Presser Foot (For Right Needle), Elasticator Presser Foot, Cording Presser Foot, Beading Presser Foot, Piping Presser Foot, Gathering Presser Foot



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655
40149061	_		40064938	
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500	
4006	4938	_		

MO Attachment Set 3pcs

This is a set of three presser feet that can be used for practical sewing or decorative stitching.





MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655	
40149060	_	40064939			
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500		
4006	4939	_			

MO Attachment Set 6pcs (For MO-50e)

This is a set of six presser feet that can be used for practical sewing or decorative stitching.

decorative stitching.

This set contains the following: Universal Blind Stitch Presser Foot (For Right & Left Needle), Elasticator Presser Foot, Beading Presser Foot, Piping Presser Foot, Gathering Presser Foot, Taping Foot



MO-2000QVP MO-1000	MO-80CB	MO-114D MO-104D	MO-735	MO-655		
<u> </u>						
MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500			
_	_	40134119	_			

Overlocker/Serger Accessories List

MO-2000QVM MO-1000P MO-80CB MO-114D MO-735 MO-655 MO-655 MO-655 MO-655 MO-655 MO-655 MO-656 MO-655 MO-655 MO-655 MO-655 MO-655 MO-655 MO-655 MO-665 A1501-130-0 MO-655 MO-665 A1501-655-080A		[I		
Standard Presser Foot 40134861 40233699 0A0 0B0 0B0A			MO-80CB		MO-735	MO-655
Monte	Standard Presser Foot	40134861	40233699			
Horal Region Hora	Blind Stitch Presser Foot (For Right Needle)	40138091	_		A9810-634-0A0A	
Cording Presser Foot 40138099 — A9820-655-0A0A Beading Presser Foot 40138106 40131949 A9870-634-0A0A Curved Beading Presser Foot 40149059 — A9511-634-0A0A Piping Presser Foot 40138103 40131950 A9865-655-0A0A Gathering Presser Foot 40138121 40131948 A9860-655-0A0C Taping Foot — 40131951 — Chain Stitch Presser Foot — 40122229 — Upper Looper Converter — A9825-634- A9130-777- A9825-634- OAO OAO OAO Waste Collector 40134096 — A910-880- A9108-130- A9108-202- OOO Extension Table Set — 40233733 — Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149060 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939		40149058	40131946		A9521-634-0A0A	1
Beading Presser Foot 40138106 40131949 A9870-634-0A0A Curved Beading Presser Foot 40149059 — A9511-634-0A0A Piping Presser Foot 40138103 40131950 A9865-655-0A0A Gathering Presser Foot 40138121 40131948 A9860-655-0A0C Taping Foot — 40131951 — Chain Stitch Presser Foot — — 40122229 — Upper Looper Converter — A9825-634-0A0 A9130-777-0A9825-634-0A0 A90A0-0A0 A90A0-0A0 A9108-130-0A0 A9108-130-0A0 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000	Elasticator Presser Foot	40138095	40233726		A9815-655-0A0A	\
Curved Beading Presser Foot 40149059 — A9511-634-0A0A Piping Presser Foot 40138103 40131950 A9865-655-0A0A Gathering Presser Foot 40138121 40131948 A9860-655-0A0C Taping Foot — 40131951 — Chain Stitch Presser Foot — — 40122229 — Coverstitch Hem Guide — — A9825-634-0A0 A9130-777-0A0 A9825-634-0A0 A910-880-0A0 A910-880-0A0 A910-880-0A0 A9108-130-0A0 <	Cording Presser Foot	40138099	-		A9820-655-0A0A	
Piping Presser Foot 40138103 40131950 A9865-655-0A0A Gathering Presser Foot 40138121 40131948 A9860-655-0A0C Taping Foot — 40131951 — Chain Stitch Presser Foot — — 40122229 — Coverstitch Hem Guide — — A9825-634-0A0 A9130-777-0A0 A9825-634-0A0 A9108-130-0A0 A9108-130-0A0 A9108-130-0A0 A9108-202-000 A9108-130-000 A9108-202-000 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-202-000 A9108-130-000 A9108-130-000 A9108-202-000 A9108-202-0	Beading Presser Foot	40138106	40131949		A9870-634-0A0A	
Gathering Presser Foot 40138121 40131948 A9860-655-0A0C Taping Foot — 40131951 — Chain Stitch Presser Foot — — 40122229 — Coverstitch Hem Guide — — A9825-634- 0A0 A9130-777- 0A0 A9825-634- 0A0 A900-777- 0A0 A9108-130- 0A0 A9108-202- 000 A9108-130- 000 A9108-130- 000 A9108-202- 000 A9108-130-	Curved Beading Presser Foot	40149059	_	A9511-634-0A0A		
Taping Foot — 40131951 — Chain Stitch Presser Foot — 40122229 — Coverstitch Hem Guide — — A9825-634- A9130-777- A9825-634- OAO OAO OAO OAO OAO OAO OAO OAO OAO OA	Piping Presser Foot	40138103	40131950	A9865-655-0A0A		
Chain Stitch Presser Foot — 40122229 — Coverstitch Hem Guide — A9825-634- A9130-777- OA0 OAO OAO OAO OAO OAO OAO OAO OAO OAO	Gathering Presser Foot	40138121	40131948	A9860-655-0A0C		
Coverstitch Hem Guide — 40122229 — Upper Looper Converter — A9825-634-0A0 A9130-777-0A0 A9825-634-0A0 Waste Collector 40134096 — A910-880-130-000 A9108-130-000 A9108-202-000 Extension Table Set — 40233733 — — Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Taping Foot	_	40131951	_		
Upper Looper Converter — A9825-634- OAO A9130-777- OAO A9825-634- OAO Waste Collector 40134096 — A910-880- L000 A9108-130- O0O A9108-202- O0O Extension Table Set — 40233733 — — Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Chain Stitch Presser Foot			_		
Upper Looper Converter — OAO OAO OAO Waste Collector 40134096 — A910-880- L000 A9108-130- 000 A9108-202- 000 Extension Table Set — 40233733 — Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Coverstitch Hem Guide		_		40122229	-
Waste Collector 40134096 — L000 000 000 Extension Table Set — 40233733 — Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Upper Looper Converter	-	-			
Foot Control Please contact your local JUKI dealer MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Waste Collector	40134096	_			
MO Attachment Set 8pcs 40149062 — 40123395 MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Extension Table Set	-	40233733		-	
MO Attachment Set 6pcs 40149061 — 40064938 MO Attachment Set 3pcs 40149060 — 40064939	Foot Control		Please co	ntact your local JUKI dealer		
MO Attachment Set 3pcs 40149060 — 40064939	MO Attachment Set 8pcs	40149062	_	40123395		
	MO Attachment Set 6pcs	40149061	_	40064938		
MO Attachment Set 6pcs (For MO-50e)	MO Attachment Set 3pcs	40149060	_	40064939		
	MO Attachment Set 6pcs (For MO-50e)			_		

	MO-654DE MO-644D	MO-623	MO-50e MO-50eN	MCS-1500
Standard Presser Foot	A1501-634- 0B0	A1501-613- 0B0A	40131302	40122001
Blind Stitch Presser Foot (For Right Needle)	A9810-6	34-0A0A	_	_
Universal Blind Stitch Presser Foot (For Right & Left Needle)	A9521-6	34-0A0A	40131946	_
Elasticator Presser Foot	A9815-6	55-0A0A	40131947	_
Cording Presser Foot	A9820-6	55-0A0A	_	-
Beading Presser Foot	A9870-6	34-0A0A	40131949	_
Curved Beading Presser Foot	A9511-6	34-0A0A	_	
Piping Presser Foot	A9865-655-0A0A		40131950	_
Gathering Presser Foot	A9860-655- 0A0C	_	40131948	I
Taping Foot	– 40131951		_	
Chain Stitch Presser Foot		_		40177370
Coverstitch Hem Guide		_		40177371
Upper Looper Converter	A9825-0	634-0A0	_	_
Waste Collector	A9108-	202-000	_	_
Extension Table Set		-	-	
Foot Control	P	lease contact you	ır local JUKI deal	er
MO Attachment Set 8pcs	40123395 —			_
MO Attachment Set 6pcs	4006	4938	_	_
MO Attachment Set 3pcs	4006	64939	_	_
MO Attachment Set 6pcs (For MO-50e)		_	40134119	_